

SECRETONT
51456**PRIORITY**

P 082132Z

FM CIA WASHDC

TO RUCSBR/SAC OFFUTT AFB, OMAHA, NEB

RUEAHQ/DIAXX

RUECYG/NAVY PIC

RUETDH/6594TH TEST SQD, WESTOVER AFB, MASS

RUWGAA/HQS 2ND AF BARKSDALE, LA

DA GRNC

BT

SECRET

CITE CIA-Z-740

FOR DI, BRASS KNOB, DOCR, DM 4, DIM, SAC HQS, OMAHA. FROM NATIONAL PHOTOGRAPHIC INTERPRETATION CENTER. SUBJECT FILM EVALUATION MISSION 3655.

1. CAMERA B 15 USED IN MISSION 3655 FLOWN ON 6 JULY 1963; PROCESSING WAS ACCOMPLISHED BY NAVY PIC.

2. ORIGINAL NEGATIVE:

A. EXPOSURE IS GOOD TO SLIGHTLY OVEREXPOSED. THE RESOLUTION IS FAIR TO GOOD.

B. 9R SIDE: THE 1L AND 1R POSITION INDICATOR LAMPS DID NOT FUNCTION THROUGHOUT THE MISSION. THE DATA CLOCK IMAGE SHOWS EVIDENCE OF SLIGHT VIBRATION, MAKING THE SECONDS DIFFICULT TO READ. A PATTERN OF TWO FAINT MINUS DENSITY DOTS, OCCUR EVERY

9 JUL 1963

1963 JUL 8 22 04Z
HFS ☒
CJS ☒
GFC ☒
PNC ☒
AGL ☒
Grace (File)

Declassification Review by NGA/DoD

SECRET

GROUP 1
Excluded from automatic
downgrading and
declassification

1.58" APART, AND 1.3" IN, FROM THE OUTBOARD EDGE, THROUGHOUT THE FILM. MINOR BANDING, PERPENDICULAR TO THE FILM EDGES IS PRESENT INTERMITTENTLY. CAMERA LIGHT LEAKS OCCUR ON THE LAST TWO FRAMES OF THE MISSION. METERING BECOMES SLIGHTLY ERRATIC TOWARD THE END OF THE MISSION. MINOR PROCESSING STREAKS, PINHOLES AND BLISTERS ARE FEW AND RANDOM THROUGHOUT THE FILM. CREASES OCCUR ON FRAMES 820 AND 821.

C. 9L SIDE: THE 3 L POSITION INDICATOR LAMP OPERATED ERRATICALLY ON THE LAST QUARTER OF THE MISSION. MINOR ROLLER STATIC MARKS ARE PRESENT ALONG TH INBOARD EDGE AFTER FRAME 678. MINOR BANDING PERPENDICULAR TO THE FILM EDGES IS PRESENT INTERMITTENTLY. EDGE STATIC OCCURS INFREQUENTLY ALONG THE INBOARD EDGE OF THE FILM. CHEMICAL STAINS DESENSITIZE SMALL PORTIONS OF FRAMES 1201-1203 AND 1213-1217. LACQUER APPEARS ALONG THE INBOARD EDGE, ON THE EMULSION SIDE OF FRAMES 1991-1995. METERING BECAME SLIGHTLY ERRATIC TOWARD THE END OF THE MISSION. VERY MINOR BLISTERS AND PINHOLES OCCUR INFREQUENTLY THROUGHOUT THE FILM.

D. NO MAJOR CAMERA MALFUNCTIONS OCCUR IN THIS MISSION. THE PROCESSING IS GOOD WITH NO PROBLEMS OBSERVED.

3. POSITIVE:

A. THE PI SUITABILITY IS FAIR TO GOOD. DEGRATATION IS DUE MAINLY TO HAZE AND CLOUD COVER. PRINTING AND PROCESSING ARE GOOD.

B. CLOUDS COVER APPROXIMATELY 50 PERCENT OF THE MISSION.

SCP-1